





2-Step Solution



Inox

| | Disc Ø [mm] | Bore Ø [mm] | Grit Körnung Grain Размер зерна | Max. speed [rpm] | Part number | EAN 3165 140 ... |
|---|----------------|----------------|--|---------------------|---------------|---------------------|
| best  Inox | 125 | 22.23 | 80 | 12 250 | 2 608 608 313 | 607 032 |
| best  Inox | 125 | 22.23 | Coarse / Grob / Grossier / крупный | 7 650 | 2 608 607 636 | 528 764 |

Carbon Steel

| | | | | | | |
|--|-----|-------|---|--------|---------------|---------|
| best  Metal | 125 | 22.23 | 36 | 12 250 | 2 608 607 255 | 247 924 |
| best  Inox | 125 | 22.23 | Extra Coarse / Sehr Grob / Extra Grossier / очень крупнозерн | 7 650 | 2 608 607 635 | 528 757 |

Aluminium

| | | | | | | |
|--|-----|-------|--------------------------------------|--------|---------------|---------|
| best  Metal | 125 | 22.23 | 60 | 12 250 | 2 608 606 733 | 179 980 |
| best  Inox | 125 | 22.23 | Medium / Mittel / Moyen / средний | 7 650 | 2 608 607 637 | 528 771 |

GWS 15-125
Inox Professional



Backing Pad

2-Step Solution



High quality weld treatment
Qualitätsnachbehandlung für Schweißnaht
Traitement de soudures de haute qualité
Высокое качество обработки сварных швов



BOSCH
Invented for life

Fast and efficient to an even surface in just 2 steps

High quality surface treatment

Schnell und effizient zu einer glatten Oberfläche in nur 2 Schritten







Qualitätsbearbeitung der Oberfläche

Rapide et efficace pour une surface plane en 2 étapes

Traitement de surface de haute qualité

Быстра и эффективная очистка поверхностей in в 2 шага

Высокое качество обработки поверхности

| | 1. Step: Fibre Disc | 2. Step: SCM Fleece Disc |
|--------------|---|---|
| Inox |  |  |
| Carbon Steel |  |  |
| Aluminium |  |  |



1. Step: Fibre Disc

Removing weld seams fast and getting a clean surface

1. Schritt: Fiber-Scheibe

Abschleifen der Schweissnaht für eine saubere Oberfläche

1. Étape : Disque fibre

L'élimination de la soudure se passe vite pour une surface propre

1. Шаг: Фибровый шлифкруг

Идеально ровная поверхность и быстрое удаление сварных швов

2. Step: SCM Fleece Disc

Refining the surface, even deep scratches

2. Schritt: SCM Fleece-Scheibe

Verfeinern der Oberfläche, selbst bei tiefen Kratzern

2. Étape : Disque en non-tissé SCM

Affinage de la surface, même sur des égratignures profondes

2. Шаг: Нетканый круг SCM

Очистка поверхности, даже с глубокими царапинами